

[Back to Service History](#)

View the details on the service or repair performed on your vehicle, as reported by the dealer. Please contact them directly with any questions.

# 2000 4Runner

VIN: JT3HN86R0Y0289809

Mileage: 68,126

 [Download](#)

Date of Service	Service Type
12/2007	Dealer

Customer  
D Palm

Job  
Date  
Operation  
Payment  
1  
12/2007

CHECK ENGINE LIGHT  
CHECK ENGINE LIGHT ~|~CHECK ENGINE LIGHT IS ON ~|~DTC P0171(SYSTEM LEAN) DUE TO RODENT DAMAGED AIR FILTER AND DIRTY MAF SENSOR. ~|~R&R MAF AND CLEAN,REPL. AIR FILTER,CLEAR DTC AND ROADTEST.

Parts

Name  
Part #  
Qty

Customer Pay

2  
12/2007

LUBE,OIL AND FILTER  
LUBE,OIL AND FILTER ~|~CHANGE OIL AND FILTER. CHECK FLUID LEVELS, TIRE PRESSURE AND LIGHTS, COOLANT PROTECTION,BATTERY AND WIPERS RECORD TIRE TREAD DEPTH READINGS: R/F ..... 32NDS; L/F ..... 32NDS; L/R ..... 32NDS; R/R ..... 32NDS. COOLANT PROTECTION LEVEL ..... DEGREES FARENHI ~|~NORMAL MAINTENANCE REQUEST ~|~COMPLETED LOF

Parts

Name  
Part #  
Qty

FILTER, OIL90915YZZD11

GASKET90430120281

SHELL GL-4OIL6

Customer Pay

3  
12/2007

P/STEERING SERVICE

P/STEERING SERVICE ~|~PERFORM BG POWER STEERING FLUID FLUSH SERVICE. THIS WILL IN CLUDE TECHNICIAN USING SPECIAL EQUIPMENT ON STEERING SYSTEM TO REMOVE ACCUMULATED RESIDUE FROM SYSTEM THEN FLUSH OUT OLD CONTAMINATED FLUID AND CONTAMINATES AND ADD NEW FLUID SPEICA LLY FORMULATE ~|~BG POWER STEERING SYSTEM FLUSH COMPLETED

Parts

Name  
Part #  
Qty

PS FLUSHBG67001

Customer Pay

---

4  
12/2007

TRANS. FLUID CHANGE  
TRANS. FLUID CHANGE ~|~USING SPECIAL EQUIPMENT TECHNICIAN WILL FLUSH OUT 100% OF OLD CONTAMINATED TRANSMISSION FLUID INCLUDING TORQUE CONVERT ER, VALVE BODY AND COOLER UNIT, ADD CLEANER TO HELP REMOVE H ARMFUL DEPOSITS FROM SYSTEM AND REFILL THE SYSTEM WITH NEW F LUID SET TO PR ~|~BG AUTOMATIC TRANSMISSION FLUSH SERVICE PERFORMED.

Parts

Name  
Part #  
Qty

TRANS FLUSHBG66001

TRANS FLUATF16

Customer Pay

---

12/2007

**BRAKE FLUID SERVICE**

BRAKE FLUID SERVICE ~|~FLUSH BRAKE FLUID ~|~ ~|~FLUSH HYDRAULIC BRAKE SYSTEM, REPLACE BRAKE FLUID

**Parts**

Name

Part #

Qty

BRAKE FLUSHBG840321

Customer Pay

---

6

12/2007

**INSPECT PARKING BRK**

INSPECT PARKING BRK ~|~TECHNICIAN FOUND E-BRAKE PIVOTS FROZEN ~|~RUST/LACK OF USE ~|~FREE-UP,  
CLEAN AND LUBE P-BRAKE PIVOTS. INCL. REPL. PINS AND CLIPS AS NECC.

**Parts**

Name

Part #

Qty

PIN90249080681

WASHER, TYPE C90213060131

Customer Pay

---



[DO NOT SELL MY PERSONAL INFORMATION](#)

[Cookie Consent Options](#)

[Toyota](#)

[Safety Recalls &  
Service Campaigns](#)

[Update Ownership  
Info](#)

[Connected Services](#)

[Service Centers](#)

[Manuals &  
Warranties](#)

[Dashboard Lights](#)

[Toyota Genuine  
Parts](#)

[Maintenance](#)

[Schedule](#)

[Maintenance Plans](#)

[ToyotaCare](#)

[ToyotaCare Plus](#)

[Toyota Service Care](#)

[Service Coupons  
Discounts](#)

[Contact Us](#)

[FAQs](#)

[Audio Software  
Updates](#)

[Audio Multimedia](#)

[Yaris iA Multimedia  
System](#)

[Toyota Racing](#)

[Toyota Outfitters](#)

[Toyota Racing  
Development](#)

[Privacy Policy](#) | [California Privacy](#) | [Legal Terms](#) | [Site Map](#) | [AdChoices](#)

©2011-2020 Toyota Motor Sales, U.S.A., Inc. All rights reserved. All information contained herein applies to vehicles

registered in the 48 U.S.-contiguous states and Alaska. Privacy Policy Terms of Use Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc. Google Play™ is a registered trademark of Google LLC.