## Service Record Details for Your 2000 4Runner

| DATE           | 09/09/2006                     | VEHICLE  | 2000 4Runner      |
|----------------|--------------------------------|----------|-------------------|
| TYPE           | Dealer                         | VIN      | JT3HN86R0Y0307872 |
| REPAIR ORDER # | 0129426                        | MILEAGE  | 63027             |
| PROVIDER       | Tufankjian Toyota of Braintree | CUSTOMER | D PALM            |
|                | 210 Union Street               |          |                   |
|                | Braintree, MA 02184            |          |                   |
| SERVICES       |                                | NOTES    |                   |

| JOB | DATE       | OPERATION          | DETAILS   | PAYMENT         |
|-----|------------|--------------------|---|-----------------|
| 1   | 09/09/2006 | CHECK ENGINE LIGHT | CHECK ENGINE LIGHT<br>~ ~CUSTOMER STATES CHECK<br>ENGINE LIGHT ON ~ ~ ~ ~SCANNED<br>CODE P0172DIAGNOSED FAULT IN<br>MASS AIR FLOW SENSOR PART<br>#22204-07010 COST TO REPLACE<br>\$240.00 | CUSTOMER<br>PAY |