Manchester, NH 03103



SEARCH



D 🗸

2001 4Runner SR5



My Vehicle

Find A Dealer

Parts & Service >

Resources 🗸

Videos

Community >

## **◆** BACK

Here's more detailed information about the service or repair you had done. The record is displayed as reported by the dealer. Please contact them directly with any questions.

| DATE           | 3/7/06   | VEHICLE  | 2001 4Runner      |
|----------------|--|----------|-------------------|
| TYPE           | Dealer   | VIN      | JT3HN86R419049390 |
| REPAIR ORDER # | 0314470  | MILEAGE  | 88,682            |
| PROVIDER       | Ira Toyota of Manchester<br>33 Autocenter Road | CUSTOMER | D PALM            |

| JOB | DATE   | OPERATION  | DETAILS   |        | PAYMENT            |     |
|-----|--------|--|---|--------|--------------------|-----|
| 1   | 3/7/06 | CUSTOMER REQUESTS A<br>LUBE OIL AND FILTER<br>CHANGE                         | CUSTOMER REQUESTS A LUBE OIL AND FILTER CHANGE ~ ~CUSTOMER REQUESTS A LUBE OIL AND FILTER CHANGE  |        | CUSTOMER<br>PAY    |     |
|     |        |  | PARTS   |        |                    |     |
|     |        | NAME<br>FILTER S/A, OIL<br>GASKET<br>OIL,MOTOR 5W30 QT W                     | PART #<br>90915YZZG1<br>9043012028<br>002791QT5W01  |        | QTY<br>1<br>1<br>6 |     |
| 2   | 3/7/06 | PERFORMED COURTESY CHECK ON THIS VEHICLE SEE BELOW LINE COMMENTS AND REPAIRS | PERFORMED COURTESY CHECK ON THIS VEHICLE SEE BELOW LINE COMMENTS AND REPAIRS ~ ~C/S PLEASE PERFOM COURTESY CHECK ~ ~AT 90,000 MILES RECOMEND REMAINDER OF 90K SERVI CE (WILL NOT NEED AIR FILTER OR TRANSMISSION FL UID CHANGE - WILL NEED DIFFERENTIAL FLUIDS CHAN GED EST\$159.95 FOR ALL DIFFERENTIAL FLUIDS) ALS O AT 90K RECOMEND TIMING BELT REPLACEMENT EST\$3 99.95 FOR TIMIN |        | CUSTOMER<br>PAY    |     |
|     |        |  |   |        |                    |     |
|     |        |  | NAME  | PART # |                    | QTY |

| 3                                       | 3/7/06 | PERFORMED<br>TRANSMISSION SERVICE<br>AND FLUID CHANGE       | PERFORMED TRANSMISSION SERVICE AND FLUID CHANGE ~ ~TECHNICIAN NOTED TRANSMISSION FLUID IS BLACK |                          | CUSTOMER<br>PAY |          |
|---|--------|---|---|--------------------------|-----------------|----------|
|   |        |   | PARTS   |                          |                 |          |
|   |        |   | NAME<br>AUTOMATIC TRANSMISSI  | <b>PART #</b> 00718ATF00 |                 | QTY<br>4 |
| -,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |        | REPLACED AIR FILTER AND<br>CLEANED DEBRIS FROM<br>HOUSING   | REPLACED AIR FILTER AND C<br>FROM HOUSING ~ ~TECHNIC<br>FILTER IS VERY DIRTY                    |                          | CUSTOMER<br>PAY |          |
|   |        |   | PARTS   |                          |                 |          |
|   |        |   | NAME<br>ELEMENT SUB-ASSY, AI  | PART #<br>1780107020     |                 | QTY<br>1 |
| 5                                       | 3/7/06 | CLEANED AND LUBED<br>THROTTLE BODY -<br>RECHECKED OPERATION | CLEANED AND LUBED THROT<br>RECHECKED OPERATION ~ ~T<br>NOTED THROTTLE BODY IS S<br>DIRTY        | ECHNICIAN                | CUSTOMER<br>PAY |          |
|   |        |   | PARTS   |                          |                 |          |
|   |        |   | NAME  | PART #                   |                 | QTY      |
| 6 3/7/06                                |        | REPLACED LEFT SIDE TAIL<br>LIGHT BULB                       | REPLACED LEFT SIDE TAIL LIC<br>~ ~TECHNICIAN NOTED LEFT<br>LIGHT INOP                           |                          | CUSTOMER<br>PAY |          |
|   |        |   | PARTS   |                          |                 |          |
|   |        |   | NAME<br>BULB  | PART #<br>9098111048     |                 | QTY<br>1 |







| My Vehicle                            | Find a Dealer             | Parts & Service            | Helpful Links             |  |
|---------------------------------------|---------------------------|----------------------------|---------------------------|--|
| Resources                             | Videos                    | Service Centers            | Toyota                    |  |
| Resources                             | videos                    | Service History            | Accessories               |  |
| Manuals & Warranty                    |                           | Service Offers             | Toyota Financial Services |  |
| Dashboard Indicators                  | Community                 | ToyotaCare                 | Audio Software Updates    |  |
| Articles                              | Ask An Owner              | Scion Service Boost        | Email Updates             |  |
| Audio & Multimedia                    | Events                    | Toyota Express Maintenance | Contact Us                |  |
| Yaris iA Multimedia System            |                           | Genuine Toyota Parts       | RSS Updates               |  |
| Toyota Safety Sense <sup>™</sup>      | Apps                      | Certified Collision Center | Site Map                  |  |
| Safety Recalls &                      | Toyota Owners iPhone® App | Service Connect            | Update Ownership Info     |  |
| Service Campaigns                     | •                         |                            | Toyota Newsroom           |  |
| Toyota Owners App for Android™<br>AQs |                           |                            | Service Coupons Discounts |  |
| Safety Connect®                       |                           |                            | Toyota Forum              |  |

Privacy Policy | Legal Terms | Site Map | AdChoices |

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.