Manchester, NH 03103



SEARCH





2001 4Runner SR5



My Vehicle

Find A Dealer

Parts & Service V

Resources >

Videos

Community >

◆ BACK

Here's more detailed information about the service or repair you had done. The record is displayed as reported by the dealer. Please contact them directly with any questions.

DATE	5/10/07	VEHICLE	2001 4Runner
TYPE	Dealer	VIN	JT3HN86R419049390
REPAIR ORDER #	0355871	MILEAGE	103,937
PROVIDER	Ira Toyota of Manchester 33 Autocenter Road	CUSTOMER	D PALM

JOB	DATE	OPERATION	DETAILS		PAYMENT	
1	5/10/07	CUSTOMER REQUESTS A LUBE OIL AND FILTER CHANGE	CUSTOMER REQUESTS A LUBE OIL AND FILTER CHANGE ~ ~CUSTOMER REQUESTS A LUBE OIL AND FILTER CHANGE ~ ~ ~ ~RECOMMEND AIR FILTER AND TIRE ROTATION NEXT OIL CHANGE ALL OK		CUSTOMER PAY	
			PARTS			
	NAME FILTER, OIL GASKET OIL,MOTOR 5W30 QT W		PART # 90915YZZD1DS 9043012028 002791QT5W01		QTY 1 1 6	
2	5/10/07	PERFORMED NEW HAMPSHIRE MOTOR VEHICLE INSPECTION VEHICLE PASSED	PERFORMED NEW HAMPSHIRE MOTOR VEHICLE INSPECTION VEHICLE PASSED ~ ~CUSTOMER REQUESTS A NEW HAMPSHIRE MOTOR VEHICLE INSPECTION		CUSTOMER PAY	
			PARTS			
			NAME	PART #		QTY
3	5/10/07	PERFORMED NEW HAMPSHIRE MOTOR VEHICLE OBD INSPECTION	PERFORMED NEW HAMPSHI VEHICLE OBD INSPECTION V ~ ~CUSTOMER REQUESTS N	EHICLE PASSED	CUSTOMER PAY	

		VEHICLE PASSED	MOTOR VEHICLE OBD INSPE			
			PARTS			
			NAME	PART #		QTY
4 5/10/07	CUSTOMER REQUESTS TIMING BELT REPLACEMENT (6CYL)	CUSTOMER REQUESTS TIMING BELT REPLACEMENT (6CYL) ~ ~ CUSTOMER REQUESTS TIMING BELT REPLACEMENT (6CYL)				
			PARTS			
			NAME BELT, TIMING	PART # 1356869095		QTY 1
5	5/10/07	REPLACED LEAKING WATER PUMP AND THERMOSTAT/REPLACED WORN DRIVE BELTS WHILE APART	REPLACED LEAKING WATER PUMP AND THERMOSTAT/REPLACED WORN DRIVE BELTS WHILE APART ~ ~C/S REPL WATERPUMP/THERMOSTAT/DRIVE BELTS WHILE APAR=WATER PUMP LEAKING			
		PARTS				
			NAME WATER PUMP ASSY ANTIFREEZE THERMOSTAT V-BELT BELT,V ALTERNATOR BELT, V-RIBBED	PART # 161006939883 8860800331 9091603075 993642087078 900809109083 900809112683		QTY 1 1 1 1 1 1 1 1 1
6 5/10/07	5/10/07	0/07 REPLACED LEAKING VALVE STEM RT REAR TIRE=NO OTHER LEAKS FOUND	REPLACED LEAKING VALVE STEM RT REAR TIRE=NO OTHER LEAKS FOUND ~ ~REPLACE VALVE STEM RT REAR TIRE=LEAKING AIR CUSTOMER PAY			
			PARTS			
			NAME	PART #		QTY







My Vehicle	Find a Dealer	Parts & Service	Helpful Links	
Resources	Videos	Service Centers Service History	Toyota Accessories	
Manuals & Warranty		Service Offers	Toyota Financial Services	
Dashboard Indicators	Community	ToyotaCare	Audio Software Updates	
Articles	Ask An Owner	Scion Service Boost	Email Updates	
Audio & Multimedia	Events	Toyota Express Maintenance	Contact Us	
Yaris iA Multimedia System		Genuine Toyota Parts	RSS Updates	
Toyota Safety Sense [™]	Apps	Certified Collision Center	Site Map	
Safety Recalls &	Toyota Owners iPhone® App	Service Connect	Update Ownership Info	
Service Campaigns	Toyota Owners App for Android [™]		Toyota Newsroom	
FAQs	Toyota Owners App for Android		Service Coupons Discounts	
Safety Connect [®]			Toyota Forum	

Privacy Policy | Legal Terms | Site Map | AdChoices |

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.