

◀ BACK



🔍 Search

📍 Find A Dealer



D ▾

2002 Tundra
SR5



My Vehicle ▾

Parts & Services ▾

Resources ▾

DATE 6/1/12

VEHICLE 2002 Tundra

TYPE Dealer

VIN 5TBBT44132S329522

REPAIR ORDER # 0168064

MILEAGE 95,106

PROVIDER Emerson Toyota
990 Center Street
Auburn, ME 04210

CUSTOMER D PALM

JOB	DATE	OPERATION	DETAILS	PAYMENT
1	6/1/12	RECALL CAMPAIGNS	RECALL CAMPAIGNS - -RECALL BOD VISUALLY INSPECT FRAME-FRAME PASSES TOYOTA'S CRITERIA - -REMOVE RUST AND CLEAN FRAME RUST PERFORATION EXCEEDING MIN.SPECIFICATION FOUND DURING - -RUST REMOVAL AND FRAM CLEANING REFER TO AOF	WARRANTY PAY
PARTS				
			NAME	PART #
				QTY



My Vehicle	Parts & Service	Resources	Helpful Links
MY VEHICLE INFORMATION	GET SERVICE & SHOP	FOR YOUR REFERENCE	ABOUT TOYOTA
Vehicle Home	Find a Dealer	Manuals & Warranties	Toyota
Vehicle Specs	Service Centers	Dashboard Lights	Toyota Financial Services
Service History	Service Specials	Recalls	Toyota Racing
Audio Multimedia	Toyota Genuine Parts	Videos	Toyota Racing Development
Yaris iA Multimedia System			Toyota Outfitters
Audio Software Updates	SERVICE HELP	GET ANSWERS	Toyota Newsroom
	Maintenance Schedule	FAQs	Email Updates
CONNECTED SERVICES		Toyota Safety Sense	RSS Updates
Service Connect	SPECIALTY SERVICES	Contact Us	
Safety Connect®	Accessories		OTHER
	Toyota Express Maintenance		Update Ownership Info
	Certified Collision Centers		Service Coupons Discounts
			Site Map
	SERVICE COVERAGE		
	ToyotaCare		APPS
	ToyotaCare Plus		Toyota Owners iPhone® App
	Scion Service Boost		Toyota Owners App for Android™

[Privacy Policy](#) | [Legal Terms](#) | [Site Map](#) | [AdChoices](#)

©2011-19 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Privacy Policy Terms of Use Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.