



| JOB | DATE | OPERATION | DETAILS | | PAYMENT |
|-----|---------|--------------------|---|---|-------------------------|
| 1 | 5/21/10 | COOLING SYSTEM | C/S THINKS HE SMELLS ANTIFREEZE- CHECKED FLUID LOOKS LOW ~ ~ ~ ~ | | CUSTOMER PAY |
| | | | PARTS | | |
| | | | NAME | PART # | QTY |
| 2 | 5/21/10 | OIL CHANGE SPECIAL | OIL CHANGE SPECIAL ~ ~ ~ RECOMMEND: 6CYL TUN E- \$210.00+TX | | CUSTOMER PAY |
| | | | PARTS | | |
| | | | NAME FILTER, OIL GASKET OIL WINDSHIELD WASHER FL | PART # 90915-YZZD3 90430-12028 OIL WASHER | QTY 1 1 6 1 |
| 3 | 5/21/10 | DRIVEABILITY | TUNE-UP ~ ~ ~ ~ | | CUSTOMER |
| | | | PARTS | | |
| | | | NAME PLUG, SPARK VALVE SUB-ASSY, VENT | PART # 90919-01235 12204-31030 | QTY 6 1 |

ELEMENT SUB-ASSY, AI THROTTLE PLATE CLEAN

17801-31090 00289-1TP00 1



Toyota Forum





| My Vehicle | Find a Dealer | Parts & Service | Helpful Links |
|---|---|--|--|
| Resources | Videos | Service Centers Service History | Toyota Accessories |
| Manuals & Warranties Dashboard Indicators | Community | Service Specials ToyotaCare | Toyota Financial Services Audio Software Updates |
| Audio & Multimedia Yaris iA Multimedia System | Ask An Owner | Scion Service Boost Toyota Express Maintenance | Email Updates Contact Us |
| Toyota Safety Sense TM Safety Recalls & Service Campaigns FAQs Safety Connect [®] | Apps Toyota Owners iPhone® App Toyota Owners App for Android™ | Maintenance Schedule Genuine Toyota Parts Certified Collision Center Service Connect | RSS Updates Site Map Update Ownership Info Toyota Newsroom Service Coupons Discounts |

Privacy Policy | Legal Terms | Site Map | AdChoices |

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.