


Service Record Details

For your
2008 Prius

VIN: JTDKB20U883355221

Mileage: 98,223



Date of Service 7/27/2016	Repair Order # 0627337	Provider A-1 Toyota 50 Amity Road New Haven, CT 06515 (203) 389-1521	Customer Marge Palm
	Service Type Dealer		

Job	Date	Operation	Payment
-----	------	-----------	---------

1	7/27/2016	90,000 MILE SERVICE	Customer Pay
---	-----------	----------------------------	---------------------

90,000 MILE SERVICE -|-PERFORM 90,000 MILE SERVICE -|- -|-PERFORMED 90,000 MILE SERVICE LOF, TOP OFF FLUIDS, BRAKE INSPECTION, ADJUST PARKING BRAKE ROTATE & BALANCE TIRES AND INSPECT FOR WEAR, TUNE-UP, DRAIN & REFILL COOLING SYTEM, DRAIN & REFILL TRANSMISSION & DIFFERENTIAL FLUIDS, ADD OIL AND FUEL ADDITIVES, REPLACE

Parts

Name	Part #	Qty
SUPER LONG LIFE COOL	00272SLLC2	2
ELEMENT SUB-ASSY, AI	1780121040	1
WHEEL WEIGHTS	WW	2
MOA	110	1
FILTER S/A, OIL	90915YZZF2	1
API CLASS.SN	TOYOTA5W20	4
GASKET	9043012028	1
VALVE SUB-ASSY, VENT	1220421011	1
RUBBER, WIPER INSERT	8521447010	1
T4/WS FLUID	MAXLIFEATF	1
PLUG, SPARK	9008091184	4
GASKET	90430A0003	2
WIPER INSERT, DRIVER	85214YZZF1	1
WIPER INSERT - B450	85223YZZD5	1

Job	Date	Operation	Payment												
2	7/27/2016	A/C SYSTEM A/C SYSTEM - -AC FAN DOES NOT KICK ON ALL THE TIME. CUST WILL DRIVE, SHUT CAR OFF AND TURN BACK ON, AND THE FAN WILL COME ON. PLEASE CHECK FOR POSSIBLE BLOWER ISSUE. - -FOUND BAD BLOWER DUE TO A FAILURE OF THE CIRCUIT BOARD WHICH CONTROLS FUNCTION OF BLOWER UNIT. REC REPLACEMENT OF THE BLOWER AND THE CIRCUIT BOARD. EST FOR REPAIR IS 790.00 DECLINED FOR TODAY	Customer Pay												
3	7/27/2016	BUY 3 GET 1 FOR \$1 BUY 3 GET 1 FOR \$1 - -BUY 3 TIRES GET 4TH FOR A \$1, YOKOHAMA - - - -MOUNTED AND BALANCED 4 NEW TIRES. THIS SET OF TIRES HAS LIFE TIME ROTATION. Parts <table border="1"> <thead> <tr> <th>Name</th> <th>Part #</th> <th>Qty</th> </tr> </thead> <tbody> <tr> <td>P185/65R15</td> <td>DT00031806YK</td> <td>2</td> </tr> <tr> <td>P185/65R15</td> <td>DT00031806YK</td> <td>1</td> </tr> <tr> <td>P185/65R15</td> <td>DT00031806YK</td> <td>1</td> </tr> </tbody> </table>	Name	Part #	Qty	P185/65R15	DT00031806YK	2	P185/65R15	DT00031806YK	1	P185/65R15	DT00031806YK	1	Customer Pay
Name	Part #	Qty													
P185/65R15	DT00031806YK	2													
P185/65R15	DT00031806YK	1													
P185/65R15	DT00031806YK	1													
4	7/27/2016	\$79.95 ALIGNMENT \$79.95 ALIGNMENT - -PERFORM \$79.95 4 WHEEL ALIGNMENT SPECIAL - - - -PERFORMED 4 WHEEL ALIGNMENT SPECIAL	Customer Pay												
5	7/27/2016	BG AIR/FUEL SVC BG AIR/FUEL SVC - -C/S TO PERFORM B/G AIR FUEL SERVICE SPECIAL \$149.00 - - - -PERFORMED BG AIR/FUEL SERVICE Parts <table border="1"> <thead> <tr> <th>Name</th> <th>Part #</th> <th>Qty</th> </tr> </thead> <tbody> <tr> <td>AIR FUEL SERVICE</td> <td>PK200</td> <td>1</td> </tr> <tr> <td>PURGE KIT</td> <td>K2901</td> <td>1</td> </tr> </tbody> </table>	Name	Part #	Qty	AIR FUEL SERVICE	PK200	1	PURGE KIT	K2901	1	Customer Pay			
Name	Part #	Qty													
AIR FUEL SERVICE	PK200	1													
PURGE KIT	K2901	1													
6	7/27/2016	REM OIL FROMINTAKE REM OIL FROMINTAKE - -REMOVE OIL DEPOSITS FROM INTAKE MANIFOLD - - - -REMOVED T-BODY AND ACEESED MANIFOLD, REMOVED BUILD UP AND DEPOSITS. Parts <table border="1"> <thead> <tr> <th>Name</th> <th>Part #</th> <th>Qty</th> </tr> </thead> <tbody> <tr> <td>INTAKE CLNR.</td> <td>4068</td> <td>1</td> </tr> </tbody> </table>	Name	Part #	Qty	INTAKE CLNR.	4068	1	Customer Pay						
Name	Part #	Qty													
INTAKE CLNR.	4068	1													

Job	Date	Operation	Payment
-----	------	-----------	---------

7 7/27/2016 **BRAKE SYSTEM SERVICE** **Customer Pay**

BRAKE SYSTEM SERVICE -|-BRAKE FLUID DIRTY, BREAKING DOWN, LOOKS ORIGINAL. REC TO FLUSH OUT -|- -|-PERFORMED BRAKE SYSTEM FLUSH

Parts

Name	Part #	Qty
BRAKE FLUSH	PK201	1
DOT4BRKFLD	84032	1

8 7/27/2016 **CABIN AIR FILTER** **Customer Pay**

CABIN AIR FILTER -|-C/S TO REPLACE CABIN AIR FILTER -|- -|-REPLACED CABIN AIR FILTER

Parts

Name	Part #	Qty
ELEMENT, AIR REFINER	871394701083	1