


Service Record Details

For your
2008 Prius

VIN: JTDKB20U883355221

Mileage: 127,983



Date of Service 5/10/2018	Repair Order # 0695197	Provider A-1 Toyota 50 Amity Road New Haven, CT 06515 (203) 389-1521	Customer Marge Palm
	Service Type Dealer		

Job	Date	Operation	Payment
1	5/10/2018	MASTER WARNING LIGHT MASTER WARNING LIGHT - -MASTER WARNING LIGHT FLASHES WHENEVER CUSTOMER APPLIES THE BRAKES HARD. ALSO THE OIL LIGHT WILL FLASH - -OIL LEVEL IS LOW IN VEHICLE - CAUSE OF LIGHT TO COME ON WHEN BRAKING HARD. NEEDS OIL CHANGE - -SEE ADDITIONAL LINES	Customer Pay

2	5/10/2018	CUSTPAY 5W20 LOF CUSTPAY 5W20 LOF - -PERFORM CUSTOMER PAY CONVENTIONAL OIL CHANGE - - - - PERFORMED OIL CHANGE	Customer Pay
---	-----------	--	--------------

Parts

Name	Part #	Qty
XPRESS LUBE	PKQL1	1
FILTER S/A, OIL	90915YZZF2	1
GASKET	9043012031	1
API CLASS.SN	TOYOTA5W20	4

3	5/10/2018	LIFETIME ROTATE LIFETIME ROTATE - -BECAUSE CUSTOMER HAS PURCHASED 4 TIRES AT A-1 TOYOTA THEY RECEIVE LIFETIME ROTATES FOR FREE FOR LIFE OF TIRES BALANCE NOT INCLUDED - - - - PERFORMED ROTATE AND SET PSI TO SPEC	Customer Pay
---	-----------	--	--------------

Job	Date	Operation	Payment
-----	------	-----------	---------

4 5/10/2018 **REPL.WIPER BLADES** **Customer Pay**

REPL.WIPER BLADES -|-INSTALL SIGHTLINE BLADES -|- -|-REPLACED WIPER BLADES

Parts

Name	Part #	Qty
BLADE SIGHTLINE 650	85212YZZ1KTM	1
BLADE SIGHTLINE 450	85212YZZ1DTM	1

5 5/10/2018 **REPL CORNER LT BULB** **Customer Pay**

REPL CORNER LT BULB -|-REPLACE CORNER LIGHT BULB -|- -|-REPLACED L/F CORNER MARKER BULB

Parts

Name	Part #	Qty
BULB	194	1