


Service Record Details

For your
2008 Prius

VIN: JTDKB20U883355221

Mileage: 116,213



Date of Service 8/10/2017	Repair Order # 0667007	Provider A-1 Toyota 50 Amity Road New Haven, CT 06515 (203) 389-1521	Customer Marge Palm
	Service Type Dealer		

Job	Date	Operation	Payment						
1	8/10/2017	REPL FRT WHEEL BRGS REPL FRT WHEEL BRGS - -C/S THE ENGINE IS MAKING ALOT OF NOISE. PLEASE INSPECT AND ADVISE, WHINING SOUND CHANGES WITH THE VEHICLE SPEED, NOT THE GEAR IT IS IN. PLEASE INSPECT - -REPLACE L/F HUB AND BEARING, BEGINING TO SEPERATE, EXCESSIVE PLAY IS THE SOURCE OF THE ROAD NOISE. THIS IS A SAFETY CONCERN - -REPLACED THE LEFT FRONT WHEEL HUB AND BEARING.	Customer Pay						
Parts									
<table border="1"> <thead> <tr> <th>Name</th> <th>Part #</th> <th>Qty</th> </tr> </thead> <tbody> <tr> <td>HUB & BEARING ASSY,</td> <td>4351047012</td> <td>1</td> </tr> </tbody> </table>				Name	Part #	Qty	HUB & BEARING ASSY,	4351047012	1
Name	Part #	Qty							
HUB & BEARING ASSY,	4351047012	1							