

# G O M O T O R S . L L C

T. (860) 839-2518 / Sales@GoMotorsUSA.com

## INVOICE / SERVICE RECORDS

Date: 5/31/19  
**Regarding:** 1997 Toyota 4Runner 4WD vin # JT3HN87R6V0054664  
 Mileage: 238,307

### Service Records / Description of Service / Cost:

Labor	Total Labor Cost	Description	Total Parts Cost - see *	Total Amount Parts & Labor
30 hours	2700	***rear main seal, replace all seals, replace head gasket, replacing timing belt water pump, free up all adjusters, replace studs and header pipes, Replace rear main seal, -engine, *parts for engine - *see part charge to right		2700
1.5 hours	135	*Engine gasket set - includes oil filter, etc. *Remove and replace Oil Pan gasket / Clean Oil pan - *see part charge to right	300	435
		*Timing belt / water pump - ***part of engine - *see part charge to right	180	180
		*spark plugs - *see part charge to right	49	49
		*miscellaneous used parts (valve cover, motor mounts) ***part of engine	255	255
		Install new front crank seal - engine - *see part charge to right		

		replace timing belt and water pump - ***part of engine - *see part charge to right		
		Remachine heads - entire ***part of engine - *see part charge to right		
		Clean heads - ***part of engine - *see part charge to right		
		Re cut valves and install new valve seals -engine - *see part charge to right		
		Free up all bolts and free all adjusters for drive belts -***part of engine - *see part charge to right		
2 hours	180	Install new radiator	145	325
		Replace all necessary hose clamps -***part of engine		
2	180	Remove air idle control valve, clean, reinstall -		180
1.75	157.50	Remove rear brake drums, clean and adjust rear brakes and free up all E brake cables		157.5
10	900	Remove and replace all interior panels, seats, carpet and clean and wash underneath		900
2	180	Clean interior after Remove all interior panels, seats, carpet		180
		Remove carpeting and clean		
4.0	360	Full detail - SUV		360

3	270	Remove from parts car and Replace and reinstall seats / upgraded to leather replacement seats	600	870
2.0	180	Install stereo system (bracket missing see part charge)	40	220
1.2	108	Repair ABS Wire / RR		108
0.5	45	Install new battery cable ends	8	53
2 hours	180	Install roof rack	80	260
2 hours	180	Clay bar, Buff, paint and applied paint preservative and wax		180
3 hours	270	Weld and reinforce frame		270
		Install Spark Plugs - engine - ***part of engine		
		Oil and filter change - 5 qt oil - ***part of engine		
		1 Gal antifreeze (part) - ***part of engine		
1	90	replace left front door switch -panels (part - door switch \$90))	90	180
0.5	45	Replace passenger side spray nozzle (part \$20)	20	65
0.5	45	Install dashboard and panels - (parts \$70)	70	115
0.5	45	Right front parking light (part \$30)	30	75
0.5	45	Install new headlight bulbs (part	15	60
		Head Gasket - Machine S	550	550
		Sub Total		8727.5

		CT Tax 6.35%		554.19625
		Total with Tax		9281.69625

Recommended Service for Near and/or Distant Future:

Description Of Service		When Recommended	Amount Parts & Labor
Description Of Service			
Description Of Service		Timing Belt / Waterpump 80,000 miles from today's mileage (call for price but usually 650 ish)	
3000 mile oil change with synthetic oil and free 30 point inspection		3000 miles from Today's Mileage	40
Install O2 sensor (drop off car today can have ready within a couple of days)			210
Inspect and report (1 hour)			90
Sub Total			40
CT Tax 6.35%			2.54
Total			42.54

\*\*Keep for your records!