


Service Record Details

For your
2008 Prius

VIN: JTDKB20U883355221

Mileage: 110,323



Date of Service 3/30/2017	Repair Order # 0652760	Provider A-1 Toyota 50 Amity Road New Haven, CT 06515 (203) 389-1521	Customer Marge Palm
	Service Type Dealer		

Job	Date	Operation	Payment
1	3/30/2017	EXHAUST SYSTEM EXHAUST SYSTEM - -CUSTOMER STATES, EXHAUST RATTLES, NOISE IN BACK...LOOKS LIKE SOME METAL SHIELDING IS LOSE. - - - -REMOVED BROKEN HEAT SHIELD ABOVE MUFFLER IN THE REAR	Customer Pay

2	3/30/2017	REPL BLOWER MTR REPL BLOWER MTR - -CUSTOMER STATES, FAN DOESNT START. YOU GUYS REPLACED A CIRCUIT BOARD WHICH WAS SUPPOSED TO FIX IT...BUT ITS STILL CAN TAKE 5-30 MINUTES TO START SOMETIMES. BOTH HEAT AND COLD. - -POWER TO BLOWER IN CONSTANT, BLOWER INTERMITTENTLY NOT COMING ON. REC NEW ASSEMBLY - -CHANGED BLOWER MOTOR	Customer Pay
---	-----------	--	--------------

Parts

Name	Part #	Qty
MOTOR SUB-ASSY, BLOW	8710347050	1

3	3/30/2017	CHK DR LOCK ACTUATOR CHK DR LOCK ACTUATOR - -FRONT PASSENGER DOOR NOT WORKING WIRELESSLY, OR ELECTRONICALLY FROM SWITCH, ONLY WORKING MANUALLY - - - -REPLACED RF DOOR LOCK ACTUATOR	Customer Pay
---	-----------	--	--------------

Parts

Name	Part #	Qty
LOCK ASSY, FR DOOR W	6903047060	1