

[← BACK](#)

Here's more detailed information about the service or repair you had done. The record is displayed as reported by the dealer. Please contact them directly with any questions.

DATE	9/29/11	VEHICLE	1993 Previa
TYPE	Dealer	VIN	JT3AC11R1P1103547
REPAIR ORDER #	0277716	MILEAGE	711,577
PROVIDER		CUSTOMER	D PALM

JOB	DATE	OPERATION	DETAILS	PAYMENT												
1	9/29/11	RAN DIAGNOSTIC TEST ,CODE25 ,OPEN CIRCUIT ,REPLACE 02 SENSOR BANK 1,REPLACE WATE	RAN DIAGNOSTIC TEST ,CODE25 ,OPEN CIRCUIT ,REPLACE 02 SENSOR BANK 1,REPLACE WATE --CUSTOMER STATES ENGINE LIGHT IS ON, CHECK AND REPORT	CUSTOMER PAY												
			PARTS													
			<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>NUT</td> <td>9017908059</td> <td>2</td> </tr> <tr> <td>SENSOR, WATER TEMPER</td> <td>8942220010</td> <td>1</td> </tr> <tr> <td>02 SENSOR 4WIRE</td> <td>2344072</td> <td>1</td> </tr> </tbody> </table>	NAME	PART #	QTY	NUT	9017908059	2	SENSOR, WATER TEMPER	8942220010	1	02 SENSOR 4WIRE	2344072	1	
NAME	PART #	QTY														
NUT	9017908059	2														
SENSOR, WATER TEMPER	8942220010	1														
02 SENSOR 4WIRE	2344072	1														
2	9/29/11	CONFIRMED LEAVING VEHICLE	CONFIRMED LEAVING VEHICLE --CONFIRMED LEAVING VEHICLE	CUSTOMER PAY												
			PARTS													
			<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> </tbody> </table>	NAME	PART #	QTY										
NAME	PART #	QTY														
3	9/29/11	CHANGE ENGINE OIL,FILTER & DRAIN PLUG GASKET,LUBED SUSPENSION,INSPECT TIRES & BA	CHANGE ENGINE OIL,FILTER & DRAIN PLUG GASKET,LUBED SUSPENSION,INSPECT TIRES & BA --CUSTOMER STATES PERFORM THE	CUSTOMER PAY												

STREET SMART OIL & FILTER CHANGE
(INCLUDES INSPECTION OF



1993 Previa



My Vehicle

Find A Dealer

Parts & Service

Resources

Videos

Community

WASHER SOLVENT

WWSOLVENT

1

4 9/29/11

PERFORMED AN ENGINE COOLANT TRANSFUSION SERVICE,CLEANED OUT ALL OLD FLUID & ANY

PERFORMED AN ENGINE COOLANT TRANSFUSION SERVICE,CLEANED OUT ALL OLD FLUID & ANY --CUSTOMER STATES TO PERFORM A COOLING SYSTEM FLUSH

CUSTOMER PAY

PARTS

NAME	PART #	QTY
COOLANT FLUSH	BG5901	1
SUPER LONG LIFE COOL	00272SLLC2	2

5 9/29/11

TECHNICIAN INSPECTED VEHICLE, MULTI POINT INSPECTION SHEET LISTED

TECHNICIAN INSPECTED VEHICLE, MULTI POINT INSPECTION SHEET LISTED --CUSTOMER STATES TO PERFORM VEHICLE INSPECTION: CHECK ENGINE LIGHT-ON/OFF TIRE PRESSURE LIGHT:ON/OFF MAINTENACE LIGHT-ON/OFF

CUSTOMER PAY

PARTS

NAME	PART #	QTY
------	--------	-----



My Vehicle	Find a Dealer	Parts & Service	Helpful Links
Resources	Videos	Service Centers	Toyota
Manuals & Warranties		Service History	Accessories
Dashboard Indicators	Community	Service Specials	Toyota Financial Services
Audio & Multimedia	Ask An Owner	ToyotaCare	Audio Software Updates
Yaris iA Multimedia System	Events	Scion Service Boost	Email Updates
Toyota Safety Sense™	Apps	Toyota Express Maintenance	Contact Us
Safety Recalls & Service Campaigns	Toyota Owners iPhone® App	Maintenance Schedule	RSS Updates
FAQs	Toyota Owners App for Android™	Genuine Toyota Parts	Site Map
Safety Connect®		Certified Collision Center	Update Ownership Info
		Service Connect	Toyota Newsroom
			Service Coupons Discounts
			Toyota Forum

[Privacy Policy](#) | [Legal Terms](#) | [Site Map](#) | [AdChoices](#) |

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.