Service History for Your 1997 4Runner

VEHICLE 1997 4Runner

VIN JT3HN87R6V0099457

CUSTOMER D PALM

DATE	SERVICE	SERVICE PROVIDER	MILEAGE	DESCRIPTION
08/08/2013	Dealer	Ira Toyota	71,306	PERFORM CONVENTIONAL OIL AND FILTER SPECIAL FOR \$29.95 (V6, V8 AND SYNTHETIC OIL, N, MISCELLANEOUS AIR CONDITIONING - REPAIR, MISCELLANEOUS REPAIRS, PERFORM 26-POINT INSPECTION OF VEHICLE. ADVISOR WILL ATTACH TOP COPY OF FORM TO, FRONT AND REAR BRAKES 4MM, TIRE MEASUREMENTS, TAIL LAMP - REPLACE (LABOR ONLY), CV BOOTS ONE SIDE - REPLACE, AIR FILTER ELEMENT - REPLACE, TIMING BELT - REPLACE, PERFORM MOUNT AND BALANCE FOUR TIRES, EVACUATION AND RECHARGE - COMPLETE (WITH R- 134A), TUNE-UP - BASIC, PERFORM DEALER RECOMMENDED DIFFERENTIAL SERVICE, PERFORM DEALER RECOMMENDED TRANSFER CASE SERVICE, PERFORM DEALER RECOMMENDED FOAMING OPTIMIZER INDUCTION SERVICE, PERFORM DEALER RECOMMENDED THROTTLE BODY SERVICE, PERFORM DEALER RECOMMENDED FUEL INJECTION SERVICE, PERFORM 4 WHEEL ALIGNMENT SPECIAL

DATE	SERVICE	SERVICE PROVIDER	MILEAGE	DESCRIPTION
06/30/2008	Dealer	Ira Toyota	61,500	REPAIR ORDER NUMBER: 078381
				STATE INSPECTION
06/20/2007	Dealer	Ira Toyota	57,470	REPAIR ORDER NUMBER: 070848
				STATE INSPECTION, VEHICLE IS OPERATING AS DESIGNED
06/30/2006	Dealer	Ira Toyota	54,879	REPAIR ORDER NUMBER: 063373
				STATE INSPECTION
06/28/2006	Dealer	Ira Toyota	54,857	REPAIR ORDER NUMBER: 063317
				50000 MILE SERVICE OIL CHANGE AND FILTER, ROTATE TIRES, INSPECT BRAKES, RESET MAINTENANCE AND TIRE LIGHTS, COURTESY INSPECTION, TIMING BELT 6 CYL 299.95 REPLACE TIMING BELT AND CHECK PULLEYS, REMOVED AND REPLACED WATER PUMP AND THERMOSTAT AND REPLACED COOLANT, BG AUTOMATIC TRANSMISSION POWER FLUSH \$149.95, CLEANED AND ADJUST ALL BRAKES, REMOVED AND REPLACED FRONT WIPER INSERTS, ***SORRY, CAR WASH IS OUT OF ORDER TODAY***, REMOVED AND REPLACED ALL DRIVE BELTS, REMOVED AND REPALCED RIGHT SIDE BRAKE LIGHT BULB
06/03/2005	Dealer	Ira Toyota	51,068	REPAIR ORDER NUMBER: 055501
				STATE INSPECTION
06/03/2005	Dealer	Ira Toyota	51,045	REPAIR ORDER NUMBER: 055498
				DID NOT PERFORM STATE INSPECTION., REPLACE BULB, PROGRAMED ALARM TO CHIRP WHEN OPENING AND CLOSING.