





1999 4Runner
My Vehicle
Find A Dealer
Parts & Service
Resources
Videos
Community

◀ BACK

Here's more detailed information about the service or repair you had done. The record is displayed as reported by the dealer. Please contact them directly with any questions.

DATE	6/18/08	VEHICLE	1999 4Runner
TYPE	Dealer	VIN	JT3HN86R1X0207200
REPAIR ORDER #	0587847	MILEAGE	120,185
PROVIDER		CUSTOMER	D PALM

JOB	DATE	OPERATION	DETAILS	PAYMENT									
1	6/18/08	SUBLET-BURT RENTAL	SUBLET-BURT RENTAL ~ ~SUBLET-BURT RENTAL	CUSTOMER PAY									
<table border="1"> <thead> <tr> <th colspan="3">PARTS</th> </tr> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td colspan="3"> </td> </tr> </tbody> </table>					PARTS			NAME	PART #	QTY			
PARTS													
NAME	PART #	QTY											
2	6/18/08	120,000 MILE MAINTENANCE INSPECTION	120,000 MILE MAINTENANCE INSPECTION ~ ~120,000 MILE MAINTENANCE INSPECTION ~ ~ ~ ~120185 COMPLETE	CUSTOMER PAY									
<table border="1"> <thead> <tr> <th colspan="3">PARTS</th> </tr> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td colspan="3"> </td> </tr> </tbody> </table>					PARTS			NAME	PART #	QTY			
PARTS													
NAME	PART #	QTY											
3	6/18/08	LUBE OIL FILTER SERVICE - 6CYLINDER- INCLUDES ENGINE OIL AND FILTER CHANGE, LUBR	LUBE OIL FILTER SERVICE - 6CYLINDER- INCLUDES ENGINE OIL AND FILTER CHANGE, LUBR ~ ~LUBE OIL FILTER SERVICE - 6CYLINDER- INCLUDES ENGINE OIL AND FILTER CHANGE, LUBRICATION INSPECTION, TOP OFF UNDERHOOD FLUID LEVELS (WHERE APPLICABLE), SET TIRE PRESSURE ~ ~ ~ ~120185 5W-30 -38 34PSI	CUSTOMER PAY									
<table border="1"> <thead> <tr> <th colspan="3">PARTS</th> </tr> </thead> <tbody> <tr> <td colspan="3"> </td> </tr> </tbody> </table>					PARTS								
PARTS													

			NAME	PART #	QTY
			FILTER S/A, OIL	90915YZZG1	1
			GASKET	9043012031	1
4	6/18/08	INSPECT AIR FILTER AND REPLACE AS NECESSARY	INSPECT AIR FILTER AND REPLACE AS NECESSARY ~ ~INSPECT AIR FILTER AND REPLACE AS NECESSARY ~ ~ ~ ~120185 REPLACED		CUSTOMER PAY
PARTS					
			ELEMENT SUB-ASSY, AI	1780107020	1
5	6/18/08	PERFORM BATTERY SERVICE-- INCLUDES BATTERY TEST, CLEAN AND RESEAL BATTERY POSTS	PERFORM BATTERY SERVICE-- INCLUDES BATTERY TEST, CLEAN AND RESEAL BATTERY POSTS ~ ~PERFORM BATTERY SERVICE-- INCLUDES BATTERY TEST, CLEAN AND RESEAL BATTERY POSTS ~ ~ ~ ~120185 BATTERY TESTED GOOD PRINT OUT OF TEST STAPLED TO REPAIR ORDER		CUSTOMER PAY
PARTS					
6	6/18/08	DIFFERENTIAL FLUID CHANGE	DIFFERENTIAL FLUID CHANGE ~ ~DRAIN AND FILL FRONT/REAR DIFFS AND TRANSFER CASE ~ ~ ~ ~120185 75-90W IN FRONT DIFF AND T-CASE, 80-90W IN REAR DIFF		CUSTOMER PAY
PARTS					
7	6/18/08	BRAKE SERVICE/ADJUST OR INSPECTION	BRAKE SERVICE/ADJUST OR INSPECTION ~ ~BRAKE SERVICE/ADJUST OR INSPECTION ~ ~ ~ ~120185 FRONTS 8/32 REARS 6/32		CUSTOMER PAY
PARTS					
8	6/18/08	TIRES ROTATE & BALANCE	TIRES ROTATE & BALANCE ~ ~TIRES ROTATE & BALANCE ~ ~ ~ ~120185 FRONTS TO THE BACK AND BACKS TO THE FRONT		CUSTOMER PAY
PARTS					
9	6/18/08	FRONT-END ALIGNMENT	FRONT-END ALIGNMENT ~ ~FRONT-END ALIGNMENT ~ ~ ~ ~120185 ALIGN FRONT END		CUSTOMER PAY
PARTS					

10	6/18/08	COOLING SYSTEM SERVICE-- INCLUDES BACKFLUSHING RADIATOR, ENGINE BLOCK, AND HEATE	COOLING SYSTEM SERVICE-- INCLUDES BACKFLUSHING RADIATOR, ENGINE BLOCK, AND HEATE ~ ~COOLING SYSTEM SERVICE-- INCLUDES BACKFLUSHING RADIATOR, ENGINE BLOCK, AND HEATERCORE WITH SYSTEM CLEANER-- INSTALLING NEW COOLANT ~ ~ ~ ~120185 -39 DEGREES	CUSTOMER PAY									
PARTS													
<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>BG RAD-KIT</td> <td>5068</td> <td>1</td> </tr> <tr> <td>ANTIFREEZE GALLON W</td> <td>002721LLAC01</td> <td>1</td> </tr> </tbody> </table>					NAME	PART #	QTY	BG RAD-KIT	5068	1	ANTIFREEZE GALLON W	002721LLAC01	1
NAME	PART #	QTY											
BG RAD-KIT	5068	1											
ANTIFREEZE GALLON W	002721LLAC01	1											
11	6/18/08	TRANSMISSION SERVICE-- INCLUDES BACK FLUSHING AND INSTALLING NEW FLUID WITH TRAN	TRANSMISSION SERVICE-- INCLUDES BACK FLUSHING AND INSTALLING NEW FLUID WITH TRAN ~ ~TRANSMISSION SERVICE-- INCLUDES BACK FLUSHING AND INSTALLING NEW FLUID WITH TRANS. CONDITIONER ~ ~ ~ ~120185 DEX 2	CUSTOMER PAY									
PARTS													
<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>BG ATM-KIT</td> <td>3020</td> <td>1</td> </tr> </tbody> </table>					NAME	PART #	QTY	BG ATM-KIT	3020	1			
NAME	PART #	QTY											
BG ATM-KIT	3020	1											
12	6/18/08	TUNE UP ENGINE-- PERFORM UNDERHOOD INSPECTION -- PERFORM COMPRESSION TEST-- REPL	TUNE UP ENGINE-- PERFORM UNDERHOOD INSPECTION -- PERFORM COMPRESSION TEST-- REPL ~ ~TUNE UP ENGINE-- PERFORM UNDERHOOD INSPECTION -- PERFORM COMPRESSION TEST-- REPLACE SPARK PLUGS INSPECT AIR FILTER ~ ~ ~ ~120185 COMPRESSION READINGS 175, 175, 175, 180 175 175	CUSTOMER PAY									
PARTS													
<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>PLUG, SPARK</td> <td>9091901192</td> <td>6</td> </tr> </tbody> </table>					NAME	PART #	QTY	PLUG, SPARK	9091901192	6			
NAME	PART #	QTY											
PLUG, SPARK	9091901192	6											
13	6/18/08	ADD 1 CAN BG MOTOR OIL ADDITIVE DURING LUBE OIL FILTER SERVICE	ADD 1 CAN BG MOTOR OIL ADDITIVE DURING LUBE OIL FILTER SERVICE ~ ~ADD 1 CAN BG MOTOR OIL ADDITIVE DURING LUBE OIL FILTER SERVICE ~ ~ ~ ~120185 ADDED	CUSTOMER PAY									
PARTS													
<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>BG MOA</td> <td>110</td> <td>1</td> </tr> </tbody> </table>					NAME	PART #	QTY	BG MOA	110	1			
NAME	PART #	QTY											
BG MOA	110	1											
14	6/18/08	ADD 1 CAN OF BG44K FUEL SYSTEM CLEANER TO FUEL TANK	ADD 1 CAN OF BG44K FUEL SYSTEM CLEANER TO FUEL TANK ~ ~ADD 1 CAN OF BG44K FUEL SYSTEM CLEANER TO FUEL TANK ~ ~ ~ ~120185 ADDED	CUSTOMER PAY									
PARTS													
<table border="1"> <thead> <tr> <th>NAME</th> <th>PART #</th> <th>QTY</th> </tr> </thead> <tbody> <tr> <td>44K BG</td> <td>208</td> <td>1</td> </tr> </tbody> </table>					NAME	PART #	QTY	44K BG	208	1			
NAME	PART #	QTY											
44K BG	208	1											

15	6/18/08	MISCELLANEOUS	MISCELLANEOUS ~ -CUST STATES REAR WINDOW RATTLES WHEN DOWN APPROX 6" ~ - ~ -120185 INSPECTED NEED TIME TO REMOVE DOOR PANEL	CUSTOMER PAY
----	---------	---------------	--	--------------

PARTS

			NAME	PART #	QTY
--	--	--	------	--------	-----

16	6/18/08	TYPE T OIL SEAL (ONE SIDE) R&R	TYPE T OIL SEAL (ONE SIDE) R&R ~ -W93- WHILE VEHICLE WAS IN SHOP, FOUND RIGHT REAR AXLE SEAL LEAKING - SEE HISTORY ~ -FOUND RIGH REAR AXLE SEAL LEAKING ~ -120185 INSPECTED FOUND GEAR LUBE LEAKING OUT OF RIGHT REAR AXLE SEAL. REMOVED RIGHT REAR AXLE FOUND AXLE SEAL DEFORMED, INSTALLED NEW SEAL AND AXLE BEARING BECAUSE BEARING WAS CONAMINATED WITH GEAR LUBE REPLACED OUTER SEAL AND BEARING RETAINERS	WARRANTY PAY
----	---------	--------------------------------	---	--------------

PARTS

			NAME	PART #	QTY
			SEAL, TYPE S OIL	9031050006	1
			SEAL, TYPE K OIL	9031348001	1
			RETAINER, RR AXLE BE	4242320010	2
			RING, O	9030188077	1
			GASKET, BRAKE OIL DE	4244355020	1
			GASKET, BRAKE DRUM	4244435050	1
			ROTOR, SKID CONTROL,	4351735010	1
			BEARING,BAL,40,90,K	903634002077	1



My Vehicle	Find a Dealer	Parts & Service	Helpful Links
Resources	Videos	Service Centers	Toyota
Manuals & Warranties		Service History	Accessories
Dashboard Indicators	Community	Service Offers	Toyota Financial Services
Articles	Ask An Owner	ToyotaCare	Audio Software Updates
Audio & Multimedia	Events	Scion Service Boost	Email Updates
Yaris iA Multimedia System		Toyota Express Maintenance	Contact Us
Toyota Safety Sense™	Apps	Maintenance Schedule	RSS Updates
Safety Recalls & Service	Toyota Owners iPhone® App	Genuine Toyota Parts	Site Map
Campaigns	Toyota Owners App for Android™	Certified Collision Center	Update Ownership Info
FAQs		Service Connect	Toyota Newsroom
Safety Connect®			Service Coupons Discounts
			Toyota Forum

[Privacy Policy](#) | [Legal Terms](#) | [Site Map](#) | [AdChoices](#) |

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.