| ΤΟΥΟΤΑ   | owners  | SEARCH  | a 0 =           |
|--|---|---------|-----------------|
| • ВАСК   |   |         |                 |
|  | led information about the service or<br>ealer. Please contact them directly w |         | is displayed as |
| DATE   | 2/3/17  |         |                 |
| ТҮРЕ   | Dealer  |         |                 |
| REPAIR ORDER #   | 0073079   |         |                 |
| <b>PROVIDER</b><br>909 East Main Stre<br>Stamford, CT 0690 |   |         |                 |
| VEHICLE  | 2003 4Runner  |         |                 |
| VIN  | JTEBU14R730017891   |         |                 |
| MILEAGE  | 123,072   |         |                 |
| CUSTOMER   | D PALM  |         |                 |
| JOB DATE   | OPERATION   | DETAILS |                 |
|  |   |         |                 |

| 1 2/3/17                                   |  | CUSTOMER STATES CHECK THE BRAKES<br>.WAS TOLD LAST SERVICE FRONT CAL<br>IPERSWERE STARTING TO SEIZE.CHEC K<br>FRONT AND REAR BRAKES. \$153.00<br>~ ~NEED FRONT AND REAR BRAKE PAD S<br>AND ROTORS, ALSO FRONT CALIPER S<br>FROZEN ~ ~SEE BELOW FOR ADDITIONAL<br>BRAK E WORK. |                       |                        |  |
|--|--|---|-----------------------|------------------------|--|
|  |  |   | PARTS                 |                        |  |
|  |  |   | NAME                  | PART #                 |  |
| 2 2/3/17                                   |  | CUSTOMER STATES TO REPLACE 6 RES<br>ISTOR SPARK PLUGS \$192.00 ~ ~ ~ ~UNABLE<br>TO DO SPARK PLUG AT TH IS TIME DO TO<br>COILS BOLT HEADS A RE ROUNDED OFF.<br>WILL HAVE TO DO IT ANOTHER DAY WITH<br>EXTRA TIME.  |                       |                        |  |
|  |  |   | PARTS                 |                        |  |
|  |  |   | NAME                  | PART #                 |  |
| 3 2/3/17 TIRE ROTATION WHEEL<br>BALANCE VE |  | CUSTOMER STATES TO PEFORM WHEEL<br>BALANCE AND TIRE ROTATION SPECIA L \$<br>69.95 PLUS TAX ~ ~DUE BY TIME / OR<br>MILEAGE ~ ~TIRE ROTATION, WHEEL<br>BALANCE, VEHICLE INSPECTION  |                       |                        |  |
|  |  |   | PARTS                 |                        |  |
|  |  |   | NAME                  | PART #                 |  |
| 4  | 2/3/17 *** OPCODE NOT ON<br>REPORT *** | CUSTOMER STATES PERFORM 4X4 DRAI N<br>AND FILL SERVICE.DRAIN AND FIL L<br>BOTHDIFFERENTIALS AND TRANSFER CASE.<br>\$355.00 ~ ~ ~ ~PERFORM 4X4 DRAIN AND<br>FILL SE RVICE.DRAIN AND FILL BOTH DIFFER<br>ENTIALS AND TRANSFER CASE  |                       |                        |  |
|  |  |   | PARTS                 |                        |  |
|  |  |   | NAME<br>75W90 SYN OIL | <b>PART #</b><br>75W90 |  |

|   |  |  | GASKET, DRAIN PLUG<br>GASKET<br>GASKET  | 1215710010.<br>90430A0003<br>9043024003   |  |
|---|--|--|---|---|--|
| 5   | 2/3/17                                       | THE TECHNICIAN<br>INSPECTED THE VEH  | PERFORM THE MULTI POINT INSPECTI ON<br>~ ~ ~ ~THE TECHNICIAN INSPECTED THE<br>VEHICLE, PERFORMED THE MULTI POI NT<br>INSPECTION - SHEET PROVIDED  |   |  |
|   |  |  | PARTS   |   |  |
|   |  |  | NAME  | PART #  |  |
| 6 2/3/17 REMOVED AND<br>REPLACED FRONT<br>BRAKE | REPLACED FRONT                               | CUSTOMER STATES TO REPLACE FRONT<br>BRAKE PADS AND REPLACE BRAKE RO TORS<br>W/NEW FRONT BRAKE CALIPERS. ~ ~<br>~ ~REMOVED AND REPLACED FRONT BR<br>AKE PADS,REPLACE ALL SPRING CLIP S &<br>HARDWARE.LUBED ALL BACKING P<br>LATES.REMOVED AND REPLACED FRONT<br>ROTORS.INSPECTED CALIPERS AND L UBED<br>SLIDES.TOPPED OFF BRAKE FLU ID AND<br>ROAD TESTED.NEW CALIPERS INSTALLED. |   |   |  |
|   |  |  | PARTS   |   |  |
|   |  |  | NAME<br>TCMC BRAKEPAD W-SHIM<br>FITTING KIT, DISC BR<br>PIN, W/HOLE<br>CLIP, PIN HOLD<br>CALIPER SLIDE PIN GR<br>DISC, FR<br>REMAN, BRAKE CALIPER<br>REMAN, BRAKE CALIPER   | PART #<br>04465AZ001TM<br>0494735050<br>9024006158<br>4774935040<br>0888701206.<br>4351235322<br>477503516084<br>477303516084 |  |
| 7   | 7 2/3/17 REMOVE & REPLACED<br>REAR DISC BRAK |  | REMOVE & REPLACED REAR DISC BRAK E<br>PADS & ALL NECC. HARDWARE.REPL ACE<br>BRAKE ROTORS,INSP CALIPERS & HYDROLIC<br>SYSTEM,TOP FLUID.TEST DRIVE ~ ~<br>~ ~REMOVE & REPLACED REAR DISC B RAKE<br>PADS & ALL NECC. HARDWARE.R EPLACE<br>BRAKE ROTORS,INSP CALIPER S &<br>HYDROLIC SYSTEM,TOP FLUID.TE ST DRIVE |   |  |

|                                     |   | PARTS   |   |                               |
|-------------------------------------|---|---|---|-------------------------------|
|                                     |   | <b>NAME</b><br>TCMC BRAKEPAD, REAR,<br>FITTING KIT, DISC BR<br>DISC, RR | <b>PART #</b><br>04466AZ004TM<br>0494722050<br>4243160201   |                               |
| 8 2/3/17                            | 2/3/17  | PERFORMED THE BRAKE<br>SYSTEM FLUID                                     | CUSTOMER STATES PERFORM BRAKE SY<br>STEM FLUID EXCHANGE \$128.00 PLUS TAX<br>~ ~ ~ ~PERFORMED THE BRAKE SYSTEM FL<br>UID POWER FLUSH,REMOVING ALL OLD<br>FLUID &MOISTURE FROM SYSTEM,REP<br>LENISHING IT WITH NEW FLUID.INSP ECTED<br>ALL RELATED COMPONENTS. |                               |
|                                     |   | PARTS   |   |                               |
|                                     |   |   | NAME<br>DOT 3 BRAKE FLUID   | <b>PART #</b><br>004751BF0301 |
| 9 2/3/17 PERFORM SOFTWARE<br>UPDATE | SMART STOP REPROGRAM.NOTE:CUSTOM<br>ER DECLINED THROTTLE BODY CLEANI NG.<br>~ ~ ~ ~OP CODE ELSBOS .8, UPDATE SOF<br>TWARE |   |   |                               |
|                                     |   |   | PARTS   |                               |
|                                     |   |   | NAME  | PART #                        |
| 9                                   |   |   | PARTS   NAME PART #   DOT 3 BRAKE FLUID 004751BF0301   SMART STOP REPROGRAM.NOTE:CUSTOM ER DECLINED THROTTLE BODY CLEANI NG.   ~ ~~ -OP CODE ELSBOS .8, UPDATE SOF TWARE   PARTS PARTS  |                               |



| My Vehicle                         | Community  | Helpful Links                            |
|------------------------------------|--|--|
|                                    | Ask An Owner   | Audio Software Updates                   |
| Resources                          |  | Toyota                                   |
| Manuals & Warranties               |  | Accessories                              |
| Dashboard Indicators               | <b>Apps</b><br>Toyota Owners iPhone <sup>®</sup> App<br>Toyota Owners App for Android <sup>™</sup> | Toyota Financial Services                |
| Audio & Multimedia                 |  | Email Updates                            |
| Yaris iA Multimedia System         |  | Contact Us                               |
| Toyota Safety Sense <sup>™</sup>   |  | RSS Updates                              |
| Safety Recalls & Service Campaigns | ns Parts & Service   | Site Map                                 |
| FAQs                               | Service Contors  | Update Ownership Info<br>Toyota Newsroom |
| Safety Connect <sup>®</sup>        | Service Centers  | Service Coupons Discounts                |
|                                    | Service History<br>Service Specials  | Toyota Forum                             |
|                                    | ToyotaCare   |  |
| Find a Dealer                      | Scion Service Boost  |  |
|                                    | Toyota Express Maintenance   |  |
| Videos                             | Maintenance Schedule   |  |
|                                    | Genuine Toyota Parts   |  |
|                                    | Certified Collision Center   |  |
|                                    | Service Connect  |  |
|                                    |  |  |

## Privacy Policy | Legal Terms | Site Map | AdChoices

©2011-18 Toyota Motor Sales, U.S.A, Inc. All rights reserved. All information contained herein applies to vehicles registered in the 48 U.S.-contiguous states and Alaska. Apple, the Apple logo and iPhone are trademarks of Apple Inc., registered in the U.S. and other countries. App Store is a service mark of Apple Inc.